

## St. Paul Heritage Preservation Commission - Building Inventory Form

State Inventory #: RA-SPC-0460      Street Number: 656      Street: BUSH AVE

### Building Information/Historical Background

Architect/Engineer: \_\_\_\_\_ Other Designer: \_\_\_\_\_  
 Builder/Contractor: \_\_\_\_\_ Landscape Architect: \_\_\_\_\_  
 Biographical Info: \_\_\_\_\_  
 Original Owner: \_\_\_\_\_ Other Owners and Biographies: \_\_\_\_\_  
 Original Function/Use: Domestic, Single Dwelling  
 Other Functions/Uses: \_\_\_\_\_ Current Function/Use: Vacant/Not in Use  
 Property Date: 1880      Date Source Key: City parcel data      Date Event:  Construction  Demolition  
 Date: \_\_\_\_\_  Addition  Move  Alteration  
 Oral Histories: \_\_\_\_\_ Sanborn/Atlas Info: \_\_\_\_\_  
 Bldg. Permit Info: No index card available      City Directory Info: \_\_\_\_\_  
 Location of Architectural Drawings: \_\_\_\_\_ Historical Photos: \_\_\_\_\_  
 Other Sources: 1983 survey - eligible;  
 Historical Background: \_\_\_\_\_

### Architectural Information

Style: No Style       Primary       Secondary       Element      Stories: 2      Bays: 2  
 Style: \_\_\_\_\_       Primary       Secondary       Element      Plan Shape: Rectangular  
 Style: \_\_\_\_\_       Primary       Secondary       Element      Roof Shape: Gable

#### Materials

Structure: Wood Frame  
 Foundation: Stone  
 Wall (Primary): Wood  
 Wall (Secondary): \_\_\_\_\_  
 Roofing: Asphalt Shingles  
 Dormer Style(s): None      Number: 0  
 Chimney Style(s): Interior      Material(s): Brick  
 Window Type: 4/4

#### Integrity

Material Condition: Good  
 Design Integrity: Excellent  
 Alterations: Some windows boarded over  
 Original Site?   
 Locations(s): \_\_\_\_\_  
 Locations(s): Ridge  
 Window Condition: Original windows/openings intact  
 Surrounding Land Use: Industrial  
 Integrity of Setting: Fair  
 Importance of Setting: Somewhat Important

#### Site Features

Outbuildings: Carriage house  
 Site Features: \_\_\_\_\_

Notes on Exterior: Rectangular plan, two-story, front gable inspired house with pediment window hoods. The house is modest but features the original 4/4 windows and front door. A front gable wall dormer is located on the west elevation. A detached carriage house is located to the rear.

Notes on Interior: \_\_\_\_\_

General Property Notes: \_\_\_\_\_